

# REMOVING COATINGS

*3 inch or 5 inch Grinder*

24 Grit	Very Coarse: Works Well on Thicker Steel
36 Grit	Coarse: Works Fast For Removing Removing Coatings. Care Should Be Taken Not To Remove Too Much Steel.
50 Grit	Medium: Best For Removing Coatings on Thinner Metal When Using A Grinder

## *DUAL ACTION SANDER*

36 Grit	Coarse: Works Fast For Removing Removing Coatings. Safer Method For Thin Metal Than Grinder, But Slower
80 Grit	Medium: Also Works Well For Removing Coatings, But Slowest Method.

**NOTE: Care Should Be Taken Not To Overheat Metal With Any Of The Methods Mentioned**